

Brunswick Nuclear Plant – Larry Dunlap



 Repeated off/on power cycling from simulator scenarios from loss of power to equipment cause the screens on the SV100 digital recorders fail.



■ These components are difficult to find as a unit (digitzer/screen combination), so we have been forced to obtain screens separately (our procurement department "magically" found a source Argo TurboServe Corp (ATC) ~\$1600 each). This requires us to physically separate the digitizer, using a sharp blade, and reattach it using contact adhesive, carefully aligning it.



The screen.



The digitizer



SV100 Recorder front view.



SV100 Recorder rear view.



■ The "Boneyard".

